

FORM E - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION  
Office of the Secretary, State House, Boston

In Area no.	Form no.
B, J	93



n Lexington

ress 2016 Mass. Ave.

e \_\_\_\_\_

ent use Dwelling

ent owner Mrs. Mildred Clark


ription:

1890's - early 1900's

urce \_\_\_\_\_

Queen Anne

4. Map. Draw sketch of building location in relation to nearest cross streets and other buildings. Indicate north.



Architect \_\_\_\_\_

Exterior wall fabric white clapboard

Outbuildings (describe) \_\_\_\_\_

Other features composite roof-3 separate

gables - central & rear chimneys - roof

overhang with double brackets-closed (over)

Altered \_\_\_\_\_ Date \_\_\_\_\_

Moved \_\_\_\_\_ Date \_\_\_\_\_

5. Lot size:

One acre or less x Over one acre \_\_\_\_\_

Approximate frontage 60'

Approximate distance of building from street

15'

6. Recorded by Ruth Beebe

Organization Lex.Hist. Com.

Date 9/16/75

DO NOT WRITE IN THIS SPACE  
USGS Quadrant \_\_\_\_\_

MHC Photo no. \_\_\_\_\_

(over)

7. Original owner (if known) \_\_\_\_\_

Original use \_\_\_\_\_

Subsequent uses (if any) and dates \_\_\_\_\_

8. Themes (check as many as applicable)

Aboriginal	_____	Conservation	_____	Recreation	_____
Agricultural	_____	Education	_____	Religion	_____
Architectural	_____	Exploration/ settlement	_____	Science/ invention	_____
The Arts	_____	Industry	_____	Social/ humanitarian	_____
Commerce	_____	Military	_____	Transportation	_____
Communication	_____	Political	_____		
Community development	_____				

9. Historical significance (include explanation of themes checked above)

Details (cont.). pediment gables-Double bay on right side (ornamented overhanging corners above lower bay) Turned posts on back porch, beaded cutwork on cornice above them - string course of vertical panels between 1st \* 2nd floors - Inset panels under lower bay & tower windows- Dentil course over side gable window-bay on left-plaster(?) flower medallion in front gable underlined by dentil course making it in closed pediment - 3 story tower on right-closed pediment on porch roof -dentil course & flower medallion in pediment. Same bead work trim on front porch as on back porch. Stone foundation.

Historical significance

*Land owned by J.W. Hendley in 1889.  
House built prior to 1903.*

The father of Mrs. Mildred Clark, William P. Scammon, lived in this house. Mr. Scammon, for many years prior to and including the 1920s and early 1930s, was Superintendent of Public Works for the town of Lexington.

The interior was drastically altered in 1981 when the owner (Marie Boucher) removed old plaster, installed new plumbing, and completely redid the back entry and kitchen area.

S. Lawrence Whipple, 1984

10. Bibliography and/or references (such as local histories, deeds, assessor's records, early maps, etc.)

*1889 map of Lexington  
1903 Sanborn map.*